

Fig.1




Fig.2




Fig.3




Fig. 4A






Fig. 4B



**Fig.5**

0996600-002801



**Fig. 6**




Fig.7






Fig. 8






**Fig. 9A**



**Fig. 9B**



**Fig. 9C**

SCAN DIRECTION  
OF LASER ANNEAL

↓




Fig. 10A




Fig. 10B




Fig.11




Fig.12








Fig. 15A




Fig. 15B




Fig. 16A




Fig. 16B






Fig. 17




Fig. 18

09966000.002801




Fig.19




Fig.20